

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
 Mail Code 5415B-2
 1110 West Washington Street
 Phoenix, AZ 85007



RECEIVED

2009 FEB -2 P 4:30

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
WIDHOFF WATER CO-YAVAPAI	X Community	X Yes, to PWS # 13045
System ID #	Non-transient Non-community	
13077	Transient Non-community	No

Overall compliance status	No major deficiencies	X Major deficiencies
Monitoring and Reporting status	X No major deficiencies	Major deficiencies
Comments: PWS previously had an MCL for arsenic. PWS shut wells down and became consecutive to the City of Prescott (13045) on 1/26/07 until treatment plant was constructed. Treatment plant for arsenic removal went online 2/29/08, hence the consecutive connection to Prescott was terminated on 3/13/08 since it was no longer necessary. First quarter 2008 arsenic samples taken after treatment, met the standard. Arsenic concentrations after operation of treatment plant continued to increase and the system turned off the treatment and discontinued use of the wells to evaluate other treatment options. As a result the consecutive connection to 13045 was re-established on 5/16/08. PWS is reviewing their options at this time.		

Operation and Maintenance status	No major deficiencies	X Major deficiencies
Date of last Sanitary Survey	1/24/07	Inspector Kent Haugerud, NRO
Major unresolved/ongoing operation and maintenance deficiencies:		
<input type="checkbox"/> unable to maintain 20psi <input type="checkbox"/> inadequate storage <input type="checkbox"/> cross connection/backflow problems <input type="checkbox"/> surface water treatment rule <input type="checkbox"/> treatment deficiencies <input type="checkbox"/> approval to construct/of construction <input type="checkbox"/> certified operator <input checked="" type="checkbox"/> other – management/operations		
Comments: 1/10/07 & 1/24/07 Follow up to formal enforcement – Significant Deficiency for Treatment and As treatment. System began operating arsenic treatment plant February 29, 2008. Please see attached documentation from the City of Prescott regarding the consecutive connection.		

Is an ADEQ administrative order in effect?	X	Yes	No
Comments: Consent Order # DW-55-08, was issued on July 1, 2008.			

Arizona Corporation Commission
DOCKETED

System Information			
Population Served	200	FEB -2 2009	
Service Connections	76		
Number of Entry Points to the Distribution System	1	DOCKETED BY	
Number of Sources	2		hr
Initial Monitoring Year	1993		
Monitoring Assistance Program (MAP) System	X	Yes	No

Evaluation completed by	Donna Calderon, Manager Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	January 22, 2009
	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
X	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.

Arizona Department of Environmental Quality
Drinking Water Monitoring and Protection Unit
Mail Code 5415B-2
1110 West Washington Street
Phoenix, AZ 85007

Drinking Water Compliance Status Report

System Name	System Type	Is system consecutive?
City of Prescott	<input checked="" type="checkbox"/> Community	<input type="checkbox"/> Yes, to PWS #
System ID #	Non-transient Non-community	
13045	Transient Non-community	<input checked="" type="checkbox"/> No

Overall compliance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Monitoring and Reporting status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Comments: None		

Operation and Maintenance status	<input checked="" type="checkbox"/> No major deficiencies	<input type="checkbox"/> Major deficiencies
Date of last Sanitary Survey	12/26/07	Inspector James Jones, NRO
Major unresolved/ongoing operation and maintenance deficiencies:		
<div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> unable to maintain 20psi <input type="checkbox"/> cross connection/backflow problems <input type="checkbox"/> treatment deficiencies <input type="checkbox"/> certified operator </div> <div> <input type="checkbox"/> inadequate storage <input type="checkbox"/> surface water treatment rule <input type="checkbox"/> approval to construct/of construction <input type="checkbox"/> other = </div> </div>		
Comments: Informal system inspection completed on this date. Last Sanitary Survey was 2/14/06.		

Is an ADEQ administrative order in effect?	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/>	No
Comments: PWS has an open consent order.				

System Information				
Population Served	40255			
Service Connections	20753			
Number of Entry Points to the Distribution System	6			
Number of Sources	4			
Initial Monitoring Year	1994			
Monitoring Assistance Program (MAP) System	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/> X	No

Evaluation completed by	Donna Calderon, Manager Drinking Water Monitoring and Protection Unit		
Phone	602-771-4641	Date	January 22, 2009
<input checked="" type="checkbox"/> X	Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the monitoring and reporting deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by 40 CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		
<input type="checkbox"/>	Based upon the operation and maintenance deficiencies noted above, ADEQ cannot determine if this system is currently delivering water that meets water quality standards required by CFR 141/Arizona Administrative Code, Title 18, Chapter 4.		

This compliance status report does not guarantee the water quality for this system in the future, and does not reflect the status of any other water system owned by this utility company.



City of Prescott

Public Works Department

PO Box 2059 Prescott, Arizona 86302

Phone: (928) 777-1130 TDD: (520) 778-5680 FAX: (928) 771-5929

December 29, 2008

Arizona Corporation Commission
Attn: Kristin K. Mayes, Commissioner
1300 W. Washington St. 1st Floor
Phoenix, AZ 85007-2929

To Whom It May Concern:

Please see the attached notice to Wilhoit Water Company concerning a disconnection of water service for March 31, 2009.

If you have any questions, please feel free to contact me at (928) 777-1130.

Sincerely,

A handwritten signature in black ink, appearing to read "Mark Nietupski".

Mark Nietupski
Director of Public Works

file



Steve Norwood, City Manager

201 S. Cortez Street
Prescott AZ 86303
928-777-1270

December 18, 2008

Glenarmland Company a.k.a. Wilhoit Water Company
P.O. Box 870
Clarkdale, AZ 86324

Re: Discontinuation of Water Service
Yavapai Mobil Home Estates & Adjacent Apartment Complex

Via: US Mail Certified

Dear Sirs:

This letter is to inform you the City of Prescott will disconnect the water service to the above-referenced properties on March 31, 2009.

Your properties have been served potable water by the City of Prescott on a temporary basis since May of 2008, with an understanding that the length of service would be 90 days, allowing time for your firm to develop an alternative means of meeting the new arsenic standard. Seven months have elapsed since that agreement under a voluntary extension of time granted by the City of Prescott.

The City of Prescott Public Works Department is available to share information on the Department's experience with arsenic treatment if needed. Please call Jim Ciaffoni, City Utilities Engineer, at (928) 777-1610.

Yours truly,

Steve Norwood
City Manager

cc Craig Dotseth, Operations Manager
Mark Nietupski, Public Works Director
Jim Ciaffoni, City Utilities Engineer